

Work Order ID 57584

Friday, April 09, 2010 11:10:40 AM



Page 1

Item ID: D3136-041

Revision ID:

Accept



Item Name: Window Assembly

Setup Start



Start Date: 4/9/2010 Start Qty: 0.00

Stop



Required Date: 4/9/2010 Req'd Qty: 0.00

Cust Item ID:

Reference: Return 2010 / RA110002

Customer:

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run

Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Draw
Number

Draw
Rev.

Plan
Code

Accept
Qty

Reject
Qty

Reject
Number

Insp.
Stamp

Draw Nbr

Revision Nbr

D3136

Rev E

100



QC

Quality Control

Memo

Pulled scrap items per RA110002.
PDR completed by customer NCR09-099

D3136-041
6x B36581
5x B53004

0.00

0.00

1004-09

110



QC

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

10/04/12